



ITEM NO.	PART NUMBER	DESCRIPTION	Default/ QTY.
1	MNT-A10-02-306	Angle Iron Stand 18 J-Bar	4
2	MNT-A10-03-303	Angle Iron Stand Extension Bar	2
3	MNT-A10-02-307	Iron Stand 19in Angle Iron Arm	2
4	MNT-A10-04-293	1/4-20x1/2in Zinc Hex Bolts	8
5	MNT-A10-04-294	1/4in Bonded Washers	8
6	MNT-A10-03-302	Angle Iron Stand 6x6 Feet	4
7	MNT-A10-04-301	6x1.5 - Mini Split Rubber Foot	8
8	MNT-A10-04-296	3/8-16x2in Carriage Bolt Zinc	4
9	MNT-A10-04-300	3/8in Bonded Washer	4
10	MNT-A10-04-298	3/8in Zinc Hex Nut	8
11	MNT-A10-04-295	3/8-16x1 3/4in Hex Bolt Galv	8
12	MNT-A10-04-299	3/8in Split Washer Galv	8
13	MNT-A10-04-297	3/8in Galvanized Hex Nuts	8
14	MNT-A10-02-308	Iron Stand 19in Stability Arm	2

## NOTE - ALL ASSEMBLY HARDWARE IS INCLUDED

UNLESS OTHERWISE SPECIFIED:
DIMENSIONS ARE IN INCHES [MILLIMETERS]
TOLERANCES ARE: ANGLES ±1.0°
FRACTIONAL SIZES X/Y ±1/64





CONFIDENTIAL - PROPRIETARY - DO NOT COPY	MAII
THE INFORMATION SET FORTH IN THIS DOCUMENT AND RELATED	
INFORMATION IS THE CONFIDENTIAL PROPERTY OF DIVERSITECH CORPORATION, AND IS NOT TO BE COPIED OR REPRODUCED OR DISTRIBUTED IN ANY FORM WITHOUT PRIOR	DWG
WRITTEN PERMISSION FROM DIVERSITECH CORPORATION.	
DO NOT SCALE DRAWING	

GMS. vg. no. QUICK SLING STAND - 5000 MODEL NO. QSTD5000 2 OF 2